


Notes from E&S Inspection on 6/11/2025



This is an aerial image to depict areas that need additional erosion and sediment controls.

The red lines are situated between existing rows of silt fencing and represent the approx location you need to install rows of staked-in hay bales.

The row of silt fence labeled A, needs to be maintained and repaired. There is too much sediment build up and it is bypassing the silt fence.

Site inspection photos taken during inspection on 6/11/2025

Silt Fence A: over-topping and bypass of sediment



Silt fence B: significant erosion down gradient of silt fence B. Staked in hay bales needed.



Silt fence A: area of by-pass that needs repair



Silt Fence A: area of over-topping. Needs repair.



Between Silt fence A and B: Erosion has worsened since inspection on June 4th.

