


Notes from E&S Inspection on 7/2/2025



This is an aerial image to depict location of existing silt fences and haybales

The red lines represent the newly installed rows of staked in haybales

The rows of silt fences have been labeled A, B, and C. Consistent with inspection notes from 6/11/2025 inspection.

Erosion and Sediment Control Inspection Photos from inspection on 7/2/2025.
This is a post-storm inspection.

Silt fence "C" overtopped



Down gradient of silt fence C. Vegetation laying flat from high velocity flow.



Undermined hay bales between Silt fences B and C





Down gradient of haybales between silt fence C and B

Failure of silt fence B



failed haybale between silt fence A and B



Failure of Silt fence A



Failure of Silt fence A (photo 2)



Sediment transport down gradient of silt fence A

