

1988 South Street Nuisance Light Enforcement Violation Photos

Before and After Light Fixture Replacement Photos
All photos taken by Heidi Leech, ZEO



Heidi A. Leech
Planning Technician/Zoning Enforcement Officer
Coventry Land Use Department
1712 Main Street
Coventry, CT 06238
www.coventry-ct.gov
hleech@coventry-ct.gov
860-742-4062

Before (3/6/25) & After (2/5/26)



Before – Light covers house



After – No light trespass on house

Before (3/6/25) & After (2/5/26)



Before – Light covers house




After – No light trespass on house

Before (3/6/25) & After (2/5/26)




Before/After photos look similar from this perspective due to angle and lens flare

Before (3/6/25) & After (2/5/26)



Before – Fixture not shielded, light projecting out




After – Fixture is full cutoff, angling light down

Additional Photos After (2/5/26)



After – Lighting from the building is seen on the driveway/Camposeo Drive but darkness is seen beyond the property line looking towards the house – no evidence of light trespass

1/12/26 After Replacement Daytime Photos



As of 1/12/26 Inspection, all fixtures have been replaced with full cutoff compliant light fixtures

1/12/26 After Replacement Daytime Photos



As of 1/12/26 Inspection, all exterior fixtures are compliant per Section 4.13.04 of the Zoning Regulations